



ENVIRONMENTAL COMPLAINTS & LOCAL SERVICES
TOTAL RETENTION FACILITIES
TOTAL RETENTION FACILITIES with LAND APPLICATION
WASTEWATER BYPASS FORM

RECEIVED
OCT 15 2018

DEQ Facility ID: S-30601 Facility Name: KW+SW #20 County: Pittsburg

Report all Total Retention Facility and
Total Retention Facilities with Land Application
wastewater bypasses to
DEQ/ Environmental Complaints and Local Services
within 24 hours at:

1-800-522-0206

Mail or Fax written report including copies of ANY test results
within 5 days to:

Department of Environmental Quality
Environmental Complaints and Local Services
P.O. Box 1677
Oklahoma City, OK 73101-1677
Fax No. (405) 702-6226

DEQ notified: Oct 11 2018 2:26 ☐ AM ☒ PM Received by: _____

Period of bypass: From Oct 11 2018 2:26 ☐ AM ☒ PM
To _____ ☐ AM ☐ PM

Type of Bypass: ☐ Pipe ☒ Lagoon/Basin ☐ Manhole ☐ Head Works ☐ Lift Station ☐ Irrigation
Strength of Bypass ☐ Raw ☒ Partially Treated ☐ Re-use (Category 4) Amount of Bypass: 28,000 gpd
Type of samples taken: ☐ BOD ☐ TSS ☐ Fecal ☐ pH ☐ None ☐ Other:

Geographical location of bypass and receiving stream if appropriate: Lagoon #3 SW #20 Carlton
Reason for bypass: Excessive rainfall, lagoon close to breaching Landing

Steps taken to prevent recurrence: repairs being made to sewer lines

Were fish or other wildlife affected as a result of the bypass? ☐ Yes ☒ No How? _____

Impact to receiving stream and/or surrounding areas: none

Steps taken to clean up or treat bypass: bypass not complete

Reported by: Chelsea Watkins Title: owner CO Services, contractor to SW #20
Signature: Chelsea Watkins Date: 10-11-18 Phone #: (918) 441-7242

DEQ EPS USE ONLY:

Type of Contact: ☐ Phone or ☒ Site Visit Date: 10/29/18 Follow up Site Visit ☒ Date: 11/15/18

Geographical location of bypass and receiving stream if appropriate: third Lagoon cell

Reason for bypass: Excessive Rainfall and I&I issues within collections

Steps taken to prevent recurrence: Repairs being made to the collections system to reduce I&I issues

Impact to receiving stream and/or surrounding areas: None

Steps taken to clean up or treat bypass: bypass not complete during site visit bypass completed during site visit 11/15/18

Corrective action needed: _____ Comply by date: _____

Reported information confirmed: ☒ Yes ☐ No If no, explain: _____

Comments:

Signature: Jonathan M. Schulz ID #: 284572 Date: 11/15/18

OKC Central Office Use Only
BYPASS ID #